



# Inspection Report

(査定書)

TIRE ROLLER (タイヤローラー)

Model WP902

Serial WP902-0968

Hour unknown  Confirm

## ■ Appearance & Operator Room (外観及び操縦席)

Repainted all over / 全体にリペイント

Damaged CNP / キャノピー破損

Damaged seat / シート破損

## ■ Equipment & Attachments (装備品・付属品)

Defective water spray tank / 散水、給水ポンプ不良

## ■ Engine (エンジン)

ISUZU DA120 #79821

## ■ Running (走行)

Difficult to insert gear / ギア入りづらい

## ■ Tire (タイヤ)

9.00-20

Several cracks on tire / 全タイヤ劣化ひび割れ多数あり

**3 Flat tires, Need replacement / 3本パンク、要タイヤ交換**

## ■ Oil Leakage (油漏れ)

**Major oil leakage from steering cylinder / ステアリングシリンダー油漏れ激しい**

## ■ Notes (特記事項)

書類有(一時抹消)

Need replacement battery / バッテリー要交換

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**