



Inspection Report

(査定書)

WHEEL LOADER (ホイールローダー)

Model LK40Z

Serial RW00294

Hour 4,925 Confirm

■ Appearance & Operator Room (外観及び操縦席)

With cabin/キャビン付

Damaged seat/シート破損

Rusty all over/全体にサビ多い

Repainted/リペイント

■ Equipment & Attachments (装備品・付属品)

Bucket width 1,570mm/バケット幅 1,570mm

■ Engine (エンジン)

YANMAR 3TN84-LRYW #68177

■ Hydraulic (油圧)

■ Running (走行)

■ Tire (タイヤ)

12.5/70-16

Worn & cracked all over / 全体に摩耗、ひび割れ有

■ Oil Leakage (油漏れ)

Minor leakage from lift cylinder/リフトシリンダー滲み

Oil leakage from rear-differential cylinder/リアデフ油漏れ

■ Notes (特記事項)

Unidentified engraved number/刻印不明

Need replacement battery / バッテリー要交換

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**