

## Inspection Report (査定書)

FARM MACHINE(農作機)

Model	JB13	
Serial	11469	
Hour	215	☐ Confirm

■Appearance & Oparator Room(外観及び操縦席)		
Canopy spec/キャノピー仕様		
■ Equipment & Attachments (装備品・付属品)		
Bucket width 1,230mm/バケット幅 1,230mm		
■ Engine(エンジン)		
KUBOTA 6A81640900 #11469		
■ Hydraulic (油圧)		
■Tiro 9 Dunning (土に取がなくれ)		
■Tire & Running(走行及びタイヤ) Front 4.00-12 , Rear 7-16		
Forward speed 3/前進3速		
Cracked tire/タイヤひび割れあり		
<b>-0:</b>		
■ Oil Leakage (油漏れ)		
■ Notes(特記事項)		

This report is only for your reference, We are not responsible for actual conditions of machine. この査定書はあくまで参考資料です、実際の機械のコンディションを保障するものではございません。