

Inspection Report (査定書)

WHEEL LOADER (ホイールローダー)

Model	910M	
Serial	H22003	79
Hour	3 414	☐ Confirm

Worn, Rusty, Scr	ched all over / 全体に傷、錆、腐食多い	
Worn bucket / /		
Equipment & /	ttachments(装備品・付属品)	
With coupler / ク	ックカプラー付	
Engine(エンジ))	
CAT C4.4 #W7N3	421	
With EPA sticker	EPAステッカー付	
Hydraulic (油圧		
	,	
Running (走行		
Running(走行 Defective parking	orake / パーキングブレーキ不良	
	orake / パーキングブレーキ不良	
Defective parking 「Fire(タイヤ) 16.9-24		
Defective parking 「Fire(タイヤ) 16.9-24	orake / パーキングブレーキ不良 nt wheel / 右前ホイール変形有	
Defective parking 「Fire(タイヤ) 16.9-24 Deformed right-fi	nt wheel / 右前ホイール変形有	
Defective parking Fire(タイヤ) 16.9-24 Deformed right-fi Dil Leakage()	nt wheel / 右前ホイール変形有 漏れ)	
Defective parking Fire(タイヤ) 16.9-24 Deformed right-fi Dil Leakage()	nt wheel / 右前ホイール変形有	
Defective parking Fire(タイヤ) 16.9-24 Deformed right-fi Dil Leakage()	nt wheel / 右前ホイール変形有 漏れ)	
Defective parking Fire(タイヤ) 16.9-24 Deformed right-fi Dil Leakage()	nt wheel / 右前ホイール変形有 漏れ)	
Defective parking Fire (タイヤ) 16.9-24 Deformed right-fi Oil Leakage ()	nt wheel / 右前ホイール変形有 漏れ)	
Defective parking Fire (タイヤ) 16.9-24 Deformed right-fi Oil Leakage () Oil leakage from s	nt wheel / 右前ホイール変形有 漏れ)	

This report is only for your reference, We are not responsible for actual conditions of machine. この査定書はあくまで参考資料です、実際の機械のコンディションを保障するものではございません。