



Inspection Report

(査定書)

CARRIER DUMP (キャリアダンプ)

Model EG40R

Serial 10198

Hour 6,891 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Very rusty, Corroded all over/全体に錆・腐食激しい

Damaged seat/シート破損

Partially repainted/一部リペイント

■ Equipment & Attachments (装備品・付属品)

Cabin spec/キャビン仕様

Damaged radio antenna/ラジオアンテナ破損

■ Engine (エンジン)

ISUZU 4BG1T #170913

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

500R rubber shoe/500R ラバーシュー

Defective left control lever, Moves towards side naturally / 左側操作レバー不具合の為 斜行あり

Cracked & worn rubber shoe/ラバーシューひび割れ・摩耗あり

360° rotating swing /360度旋回

■ Loading Platform (荷台)

Very rusty all over/全体に錆多い

Deformed & cracked side panels/アオりにクラック, 変形あり

Side panels cannot be opened/左右アオリ開閉不可

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**