



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model EX100-2

Serial 30778

Hour 3,639 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Rusty, Scratched, Dent / 錆、傷、凹み有り

■ Equipment & Attachments (装備品・付属品)

Reinforced arm / アーム補強

Missing bucket tooth / バケット爪無し

■ Engine (エンジン)

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

Oil leakage from bottom rear differential / リヤ下作動油漏れ有り

Minor oil leakage from boom cylinder / ブームシリンダーオイルにじみ

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**