



# Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model HB205-1

Serial 2918

Hour 6,489  Confirm

## ■ Appearance & Operator Room (外観及び操縦席)

High cabin spec / ハイキャビン仕様

## ■ Equipment & Attachments (装備品・付属品)

Two-way piping / 共用配管付き

With multi-lever / マルチレバー付き

## ■ Engine (エンジン)

## ■ Hydraulic (油圧)

## ■ Undercarriage & Running (走行及び足回り)

## ■ Swing (旋回台)

## ■ Oil Leakage (油漏れ)

## ■ Notes (特記事項)

Reinforced arm / アームに補強あり

Bucketless / バケツ無し

Defective generate unit, Not working bucket cylinder, Swing does not work occasionally / 発電ユニットの故障でバ

Need replacement battery / バッテリー要交換

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**