



Inspection Report (査定書)

ROUGH TERRAIN CRANE (ラフタークレーン)

Maker TADANO

Model GR120N-1

Serial FD0386

Hour 9,506HR

Confirm Not Confirm

■ Appearance (外観)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		
Covers (カバー)		✓		

■ Operator Room (オペレータールーム)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		

■ Engine (エンジン)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		MITSUBISHI 4M50 要交換 Need a replacement
Oil Cooler (オイルクーラー)		✓		
Blowby (ブローバイ)		✓		
Battery (バッテリー)			✓	
Throttle (スロットル)		✓		

■ Hydraulic (油圧)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		
Oil Leakage [Hoses] (ホース油漏れ)		✓		
Oil Leakage [Cylinder] (シリンダー油漏れ)		✓		

■ Running (走行)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		
Foot Brake (フットブレーキ)		✓		
Parking Brake (パーキングブレーキ)		✓		

■ Crane Device (クレーン装置)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		4.9t , BALL サビ有 Rusty
Boom (ブーム)		✓		
Hook (フック)		✓		
Wire (ワイヤー)		✓		

■ Swing (旋回台)	Good	Fair	Bad	Comments
Condition (コンディション)		✓		

■ Tire (タイヤ) [Size (サイズ)]	Good	Fair	Bad	Comments
Left Front (左前) 275/80R22.5		✓		
Right Front (右前) 275/80R22.5		✓		
Left Rear (左後) 275/80R22.5		✓		
Right Rear (右後) 275/80R22.5		✓		

This report is only for your reference. **We are not responsible for actual conditions of machine.**
この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**