



# Inspection Report

(査定書)

AERIAL PLATFORM (高所作業機械)

Model	NKR58E
Serial	7272292
Hour	135,050km <input type="checkbox"/> Confirm

## ■ Appearance & Operator Room (外観及び操縦席)

Very rusty, Holes, Dents / 錆多い 穴あき、凹み有り

## ■ Equipment & Attachments (装備品・付属品)

## ■ Engine (エンジン)

## ■ Hydraulic (油圧)

## ■ Undercarriage & Running (走行及び足回り)

700R15LT12PR

## ■ Raising Equipment (上昇装置)

AICHI SH140 #581986

## ■ Platform (プラットフォーム)

## ■ Oil Leakage (油漏れ)

## ■ Notes (特記事項)

Need replacement battery / バッテリーあがり

This report is only for your reference, **We are not responsible for actual conditions of machine.**  
この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**