



Inspection Report

(査定書)

FORK LIFT (フォークリフト)

Model FG20L-8

Serial 150179

Hour 1,103 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Rusty, Scratched / 錆、傷有り

Damaged seat / シート破れ有り

■ Equipment & Attachments (装備品・付属品)

■ Engine (エンジン)

Not running / 始動しない

Empty radiator / ラヂエター水入ってない

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

■ Lift (リフト)

■ Tire (タイヤ)

Front 5.50-15 8PR. Double tire / Wタイヤ

Rear 6.00-9 10PR

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**