



Inspection Report

(査定書)

BULL DOZER (ブルドーザー)

Model D3C

Serial 6SL01859

Hour 3,026 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Repainted, Rusty, Scratched / リペイント、錆、傷あり

Damage on operator seat's armrest / 運転席のひじ掛けに損傷あり

■ Equipment & Attachments (装備品・付属品)

■ Engine (エンジン)

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

Weld modification on shoe plate / シュープレートに溶接加工あり

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**