



Inspection Report

(査定書)

VEHICLE (車両)

Model PA-FE72DEV

Serial 510343

Km 135,443 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Damaged door lining / ドアの内張りの損傷あり

Cracked head light / ヘッドライトにヒビあり

■ Equipment & Attachments (装備品・付属品)

With rear & side motor / リア、サイドモニター付き

With remote control / リモコン付き

■ Engine (エンジン)

■ Hydraulic (油圧)

■ Undercarriage [Tire] & Running (走行及び足回り[タイヤ])

■ Equipment Device (架装装置)

Confirmed operation / 動作確認済

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**