



# Inspection Report

(査定書)

WHEEL LOADER (ホイールローダー)

Model 607

Serial B06-00582

Hour 11,227  Confirm

## ■ Appearance & Operator Room ( 外観及び操縦席 )

Very rusty & scratched all over / 全体に傷、さび多い

Damaged seat / シート破損

Patch on left & right lift arm, Welded / 左右リフトアームにパッチ、溶接補修有り

## ■ Equipment & Attachments ( 装備品・付属品 )

## ■ Engine ( エンジン )

## ■ Hydraulic ( 油圧 )

## ■ Running ( 走行 )

## ■ Tire ( タイヤ )

10-16.5

4 tires are worn / 4本摩耗有り

## ■ Oil Leakage ( 油漏れ )

Oil leakage from under body / 本体下部より油漏れ

Oil leakage from bucket cylinder / バケットシリンダー油漏れ

## ■ Notes ( 特記事項 )

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**