



# Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model 308CCR

Serial CPE01585

Hour 6,862  Confirm

## ■ Appearance & Operator Room (外観及び操縦席)

Very rusty & scratched all over / 全体に傷、さび多い

Piping stay was repaired by welding / 配管ステイ溶接補修有り

Patched boom / ブームにパッチ有り

## ■ Equipment & Attachments (装備品・付属品)

5 pipings spec / 5本配管仕様

Without bucket / バケットなし

## ■ Engine (エンジン)

## ■ Hydraulic (油圧)

## ■ Undercarriage & Running (走行及び足回り)

With rubber pad / ラバーパッド付き

## ■ Swing (旋回台)

## ■ Oil Leakage (油漏れ)

Oil leakage from boom & arm cylinders / ブーム、アームシリンダー油漏れ

Oil leakage near swivel joint / スイベル付近油漏れ有り

Oil leakage from control valve / コンバル付近油漏れ有り

## ■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**