



Inspection Report

(査定書)

TIRE ROLLER (タイヤローラー)

Model JW215

Serial JW2151-10057

Hour 3,775 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Scratched & rusty all over, Heavy corrosion / 全体に傷、さび、腐食多い

■ Equipment & Attachments (装備品・付属品)

Canopy spec / キャンプー仕様

■ Engine (エンジン)

ISUZU 6BG1

■ Running (走行)

■ Tire (タイヤ)

14/70-20

Worn all over / 全体に摩耗有り

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

Temporate suspension / 一時抹消あり

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**