



# Inspection Report

(査定書)

BULL DOZER (ブルドーザー)

Model	BD2J
Serial	JB520073
Hour	228 <input checked="" type="checkbox"/> Confirm

## ■ Appearance & Operator Room (外観及び操縦席)

Not authentic cabin / 後付けキャビン

## ■ Equipment & Attachments (装備品・付属品)

## ■ Engine (エンジン)

Mitsubishi S4S-E2 #123389

## ■ Hydraulic (油圧)

## ■ Undercarriage & Running (走行及び足回り)

Forward reverse 3 speed / 前後進3速

300G

Dry area shoe / 乾地シュー

## ■ Oil Leakage (油漏れ)

## ■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**