



Inspection Report (査定書)

ROUGH TERRAIN CRANE (ラフタークレーン)

Model	TR-500M-3
Serial	581667
Hour	3,835 <input type="checkbox"/> Confirm

■ Appearance & Operator Room (外観及び操縦席)

Very rusty, Scratched all over / 全体にキズサビ多い

Several patches on frame / フレームにパッチ多数有

■ Equipment & Attachments (装備品・付属品)

X-TYPE OUTRIGGER

Defective AML monitor, Need repair / AMLモニター不良、要修理

Defective weight measurement, Need repair / 荷重計不良、要修理

■ Engine (エンジン)

NISSAN PF6

■ Hydraulic (油圧)

■ Undercarriage [Tire] & Running (走行及び足回り [タイヤ])

505/95R25

Worn all over, Little air leakage / 全体に摩耗有、エア漏れ少しあり

■ Crane Device (クレーン装置)

X-TYPE OUTRIGGER

Locked boom extension (2nd~3rd) / ブームの伸縮ロック(2段~3段)

Very rusty wire / ワイヤー錆多い

■ Swing (旋回台)

Loose / ガタ有

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

Need replacement battery / バッテリー要交換

Distance 74,068km / 走行距離 74,068km

一時抹消有、クレーン検査切れ

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**