



Inspection Report

(査定書)

DUMP TRUCK (ダンプトラック)

Model PB-MK36A

Serial MK36A-03108

Km 121,885 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Scratched & rusty all over, repainted / 全体に傷、さび、リペイント有り

■ Equipment & Attachments (装備品・付属品)

SHINMAYWA

Three way dump / 3転ダンプ仕様

■ Engine (エンジン)

J07E-018404TA

■ Hydraulic (油圧)

■ Tire & Running (タイヤ及び走行)

225/80R17.5

6 snow tires / 6本スノータイヤ

6MT

■ Loading Platform (荷台)

Worn all over / 摩耗有り

Repainted / リペイント有り

■ Oil Leakage (油漏れ)

Minor oil leakage from dump cylinder / ダンプシリンダー油にじみ有り

■ Notes (特記事項)

一時抹消有り

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**