



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model 320D

Serial BWZ06460

Hour 15,143 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Repainted, Rusty, Scratched / リペイント、錆、傷あり

■ Equipment & Attachments (装備品・付属品)

With two way piping / 共用配管付き

With multi-lever (stuck) / マルチレバー付き(固着あり)

■ Engine (エンジン)

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

Stuck link / リンクの固着あり

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

Reinforced arm / アームに補強あり

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**