



Inspection Report

(査定書)

WHEEL LOADER (ホイールローダー)

Model WA380-6

Serial 66141

Hour 17,288 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Rusty, Scratched / 錆、傷あり

■ Equipment & Attachments (装備品・付属品)

■ Engine (エンジン)

KOMATSU 6D107E-1 #26556421

■ Hydraulic (油圧)

■ Running (走行)

■ Tire (タイヤ)

23.5R25

Worn front tire / 前輪摩耗

Small cracked left front tire / 左前輪細かいヒビ傷あり

■ Oil Leakage (油漏れ)

Oil leakage from bucket & steering cylinders / バケット、ステアリングシリンダー油漏れ有

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**