



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model	ZX350H-5A		
Serial	71112		
Hour	1,766	<input type="checkbox"/>	Confirm

■ Appearance & Operator Room (外観及び操縦席)

Repainted, rusty, scratched / リペイント、錆、傷あり

Damaged cover / カバーの損傷あり

Reinforced arm / アーム補強有

Worn bucket / バケットの摩耗あり

■ Equipment & Attachments (装備品・付属品)

With 2-way piping / 共用配管付き

■ Engine (エンジン)

ISUZU 6HK1 #954051

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

600G

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**