



Inspection Report

(査定書)

GENERATOR (発電機)

Model EG60BS-1

Serial 4696

Hour 8,839 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Very rusty, Scratched all over / 全体にキズ、サビ多い

■ Equipment & Attachments (装備品・付属品)

■ Engine (エンジン)

KOMATSU 6D95L

■ Generator (発電装置)

■ Oil Leakage (油漏れ)

Diesel oil leakage / 軽油漏れ有

■ Notes (特記事項)

Need replacement battery / バッテリー要交換

Replaced hour meter / アワーメーター交換履歴有

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**