



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model	313DCR
Serial	LCE00290
Hour	7,816 <input checked="" type="checkbox"/> Confirm

■ Appearance & Operator Room (外観及び操縦席)

Accident machinery, Damaged all over / 転倒機械、全体に破損多い

Patched arm/アームにパッチあり

Damaged front glass/フロントガラス破損

■ Equipment & Attachments (装備品・付属品)

Bucket less/バケット無し

Missing right cover/右側カバー欠品

With two-way piping/共用配管付

Damaged oil gauge/オイルゲージ破損

■ Engine (エンジン)

CAT C4.2 #JKH04968

Difficulty on starting engine, Thick white smoke / エンジンかかり悪い、白煙多い

Unable to start engine without spinning feed pump several times / エンジン始動時、フィードポンプを数回押さないとエンジン始動しない

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

500G

Worn all over / 全体に摩耗有

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

Minor leakage from bottom of fuel tank / 燃料タンク底滲み

Damaged oil tank sealing, Major oil leakage / 作動油タンク上部のパッキン劣化の為、油漏れ多い

■ Notes (特記事項)

Accident machine/転倒車

Need replacement battery / バッテリー要交換

This report is only for your reference, We are not responsible for actual conditions of machine.

この査定書はあくまで参考資料です、実際の機械のコンディションを保障するものではありません。