



Inspection Report

(査定書)

CARRIER DUMP (キャリアダンプ)

Model C50R-5

Serial 50763

Hour 1,897 ☒ Confirm

■ Appearance & Operator Room (外観及び操縦席)

■ Equipment & Attachments (装備品・付属品)

Cabin spec / キャビン仕様

■ Engine (エンジン)

YANMAR 4TNV94CHT #01817

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

450R

Cracked rubber shoe / ラバーシューひび割れ有

■ Loading Platform (荷台)

180 degree turn/180度旋回(作動確認済)

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

Need replacement battery / バッテリー要交換

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**