



Inspection Report

(査定書)

MINI EXCAVATOR (ミニショベル)

Model Vi045-6A

Serial 6F362

Hour 2,917 Confirm

■ Appearance & Operator Room (外観及び操縦席)

With cabin/キャビン付

Damaged seat/シート破損

■ Equipment & Attachments (装備品・付属品)

With multi-lever/マルチレバー付

■ Engine (エンジン)

YANMAR 4TNV88C #27502

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

350R Rubber shoe/350R ラバーシュー

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

Minor leakage from bucket cylinder/バケットシリンダー油滲み

■ Notes (特記事項)

建機工譲渡証明書有

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**