Inspection Report
(査定書)
WHEEL LOADER (ホイールローダー)

Model	WA30-6E0
Serial	103587
Hour	580 ☑ Confirm

■Appearance & Oparator Room (外観及び操縦席)

Rusty, scratched/錆, 傷有

Worn painting on engine cover/エンジンカバー塗装剝がれ有

■Equipment & Attachments (装備品・付属品)

Cabin spec/キャビン仕様

Bucket width 1,680mm/バケット幅　1,680mm

Corroded, Damaged rear wiper/リアワイパー腐食,損傷有

■Engine (エンジン)

KOMATSU　3D88E　#42794

■Hydraulic (油圧)

■Running (走行)

■Tire (タイヤ)

12.5　70-16

Snow tire/スノータイヤ

■Oil Leakage (油漏れ)

■Notes (特記事項)

建機工譲渡証明書有

Need replacement battery / バッテリー要交換

This report is only for your reference, We are not responsible for actual conditions of machine.
この査定書はあくまで参考資料です、実際の機械のコンディションを保障するものではございません。