



Inspection Report

(査定書)

WHEEL LOADER (ホイールローダー)

Model 918M

Serial H2601152

Hour 3,343

☒ Confirm

■ Appearance & Operator Room (外観及び操縦席)

Cabin apec/キャビン仕様

Stained smell of fertilizer / 堆肥臭有

■ Equipment & Attachments (装備品・付属品)

Bucket width 2,370mm/バケット幅 2,370mm

■ Engine (エンジン)

CAT C4.4 #W7N75894

■ Hydraulic (油圧)

■ Running (走行)

■ Tire (タイヤ)

17.5-2.5

■ Oil Leakage (油漏れ)

Oil leakage from rear-accel / リアアクセルオイル漏れ有

■ Notes (特記事項)

Need replacement battery / バッテリー要交換

書類有(R8年3月)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**