



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model ZX200-3

Serial 221807

Hour 9,248 ☒ Confirm

■ Appearance & Operator Room (外観及び操縦席)

Repainted/リペイント

Damaged seat/シート破損

Rusty/錆びあり

■ Equipment & Attachments (装備品・付属品)

Arm crane spec/アームクレーン仕様

With two-way piping/共用配管付

With multi-lever/マルチレバー付

■ Engine (エンジン)

ISUZU 4HK1 #494545

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

800G

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**