



Inspection Report

(査定書)

EXCAVATOR (油圧ショベル)

Model ZX120-6

Serial 513166

Hour 1,982 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Patched arm/アームにパッチあり

■ Equipment & Attachments (装備品・付属品)

With two-way piping/共用配管付

With multi-lever/マルチレバー付

With blade/ブレード付

With extra attachment (MSE-45FGZX) / 別途、アタッチメント(フェラーバンチャ)有

■ Engine (エンジン)

ISUZU 4JJ1 #296028

■ Hydraulic (油圧)

■ Undercarriage & Running (走行及び足回り)

600G

■ Swing (旋回台)

■ Oil Leakage (油漏れ)

■ Notes (特記事項)

建機工譲渡証明書有

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**