



Inspection Report

(査定書)

WHEEL LOADER (ホイールローダー)

Model ZW220-5B

Serial H72-10027

Hour 17,118 Confirm

■ Appearance & Operator Room (外観及び操縦席)

Damaged cover / カバーの損傷あり

Repainted / リペイント

■ Equipment & Attachments (装備品・付属品)

■ Engine (エンジン)

CUMMINS QSB6.7

■ Hydraulic (油圧)

■ Running (走行)

■ Tire (タイヤ)

Worn each tires / 各タイヤの摩耗あり

23.5R25

■ Oil Leakage (油漏れ)

Oil leakage from oil-cooler, Applied first-aid, Need repair / オイルクーラー油漏れの為、直結応急処置済、要修理

■ Notes (特記事項)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**