



Inspection Report (査定書)

WHEEL LOADER (ホイールローダー)

Model	H155XL
Serial	F006G03851U
Hour	3,068 <input type="checkbox"/> Confirm

■ Appearance & Operator Room (外観及び操縦席)

Very rusty, Scratched all over / 全体に傷、錆び多い

Damaged seat / シート破損

■ Equipment & Attachments (装備品・付属品)

CANOPY / キャノピー仕様

AT

Fork-shift spec / フォークシフト仕様

■ Engine (エンジン)

Perkins 1004 DIESEL ENGINE

■ Hydraulic (油圧)

■ Running (走行)

■ Lift (リフト)

■ Tire (タイヤ)

FRONT 8.25-15, Worn / 摩耗有

REAR 8.25-15, Worn / 摩耗有

■ Oil Leakage (油漏れ)

Major oil leakage from fork-shift cylinder / フォークシフトシリンダーオイル漏れ激しい

Oil leakage around transmission / ミッションまわりオイル漏れ

■ Notes (特記事項)

Mast height 3,750mm / マストの高さ 3.750mm

Dismantle & loading fee of Mast ¥120,000 (Tax not included) / マスト解体、積込み経費 ¥120,000(税別)

This report is only for your reference, **We are not responsible for actual conditions of machine.**

この査定書はあくまで参考資料です、**実際の機械のコンディションを保障するものではありません。**