Inspection Report
(査定書)
WHEEL LOADER (ホイールローダー)

Model	WA380-6	
Serial	66939	
Hour	14,372	☐ Confirm

■Appearance & Oparator Room (外観及び操縦席)

Repainted, rusty, scratched / リペイント、錆、傷あり

■Equipment & Attachments (装備品・付属品)

With piping / 配管付き

2 seat cabin / 2人乗りキャビン仕様

With piping / 配管付き

■Engine (エンジン)

KOMATSU 6D107 #86109143

■Hydraulic (油圧)

■Running (走行)

■Tire (タイヤ)

Worn each tires / 各タイヤの摩耗あり

23.5-25

■Oil Leakage (油漏れ)

■Notes (特記事項)

This report is only for your reference, We are not responsible for actual conditions of machine.
この査定書はあくまで参考資料です、実際の機械のコンディションを保障するものではございません。